

## **Rational**

Short limbs

Insufficient surface area

Cylindrical shaped limbs

Tapered limbs

Afibula limbs

Multi-surfaced ambulation

Afibula limbs

Adherent scars

Neuromas

Bone Scaring

Excessive redundant tissue

Driving

## **Coding Options**

### **BK Coding Options**

L5645 Addition to lower extremity, below knee, flexible inner socket, external frame

L5670 Addition to lower extremity, below knee, molded supracondylar

L5646 Addition to lower extremity, below knee, air, fluid, gel or equal custom socket

### **AK Coding Options**

L5651 Addition to lower extremity, above knee, flexible inner socket, external frame

### **Upper Extremity Coding Options**

L6687 Upper extremity addition, frame type socket, below elbow or wrist disarticulation

L6688 Upper extremity addition, frame type socket, above elbow or elbow disarticulation

**Environmentally Managed Systems, Inc.**

c: 320.260.1733 | [caspers.carl@gmail.com](mailto:caspers.carl@gmail.com) | [EMSSOCKETS.COM](http://EMSSOCKETS.COM)

3983 Pine Point Road, Sartell, MN 56377